

Wiro-Dip[®]

Characteristics

N/A

Instructions

- Dry the refractory model for 50-60 minutes at 250°-300°F.
- Dip the model once for 2-3 seconds.
- Blow off the excess dip and place back in the drying oven for 5-10 minutes.